

ENGINEERING CHANGE NOTICE

| | | | |
|----------------------------------|---------------------------------|--|------------|
| Date: 19.04.01 | | | ECN #: 180 |
| Project No.: D407-627 / D350-602 | Created By: KE | Checked By: ST | |
| Project Name: Heli-Utility - Pod | Approved By: (proj. manager) KE | Approved By: (management if req'd) N/A | |

Description of Change:

Released DS1 9151 rev A → Repair Scheme for 350/407 Pod doublers for SAF, which had difficulties with doublers peeling.

| Notification/Acceptance | Affected ✓ | Authorization |
|-------------------------|------------|----------------|
| QA | ✓ | |
| Production | N/A | |
| Planning | ✓ | |
| Marketing | ✓ | verbal from JB |

| Engineering Actions | Yes | No | Responsible | To happen by: | Complete |
|------------------------------------|-----|----|-------------|---------------|--------------------------|
| Update Blue File | | ✓ | | | |
| Update Pink File | ✓ | | KE | 19.04.16 | KE 19.04.16 |
| Update D-Part Master Binder | | ✓ | | | |
| Update Grey Project Binder 627/602 | ✓ | | KE | " | KE 19.04.16 |
| Update DEO Binder | ✓ | | " | " | KE 19.04.16 |
| Update Master Document List | ✓ | | " | " | N/A - repair scheme only |
| Update Drawing Approval Record | ✓ | | " | " | KE 19.04.16 |
| Notify TCA of Change | | ✓ | " | " | |
| Notify FAA of Change | | ✓ | | | |
| elec file move | ✓ | | " | SEAS " | KE 19.04.16 |

Notes:

- MANAGEMENT / PROD / QA got Delastik to make pod / doublers according to QSI 006(w)
- MKTG DS1 exists in pink file if customer calls with similar problem.
- PROD No need to put DS1 in existing kits,
ENGR WILL KEEP FILE ON RECORD FOR CUSTOMERS WHO HAVE PROBLEMS
BLUE FILE NOT UPDATED FOR THE SAME REASON